



# Unit Assessment Sheet

Complete

Score	67 / 97 (69.07%)	Flagged items	1	Actions	0
-------	------------------	---------------	---	---------	---

## 2-4 External Pictures of Unit



Photo 1



Photo 2



Photo 3



Photo 4

## 2-4 Internal Pictures of Unit




Photo 5




Photo 6




Photo 7




Photo 8

2309214 13ft x 9ft Used AV 2+1  
Toilet Block

**Size (Length x Width X Height):**

13ft x 9ft

**Specification:**

Used AV 2+1 Toilet Block

**Power in:**

32A power plug

**Consumer unit:**

5 Way



Photo 9

**Lighting:**

Fluorescent light

**Number of lights:**

2

**Number of electrical sockets:**

0

**Heating:**

N/A

<b>Number of heaters:</b>	0
<b>Kitchen unit:</b>	N/A
<b>Restroom:</b>	Yes
<b>Type:</b>	2 Gents + 1 Ladies
<b>Color:</b>	White RAL Code TBC
<b>Lifting:</b>	<ul style="list-style-type: none"> <li>ISO Corners Top</li> <li>Lifting Eye Corner</li> <li>Jacklegs</li> <li>Forklift pockets</li> </ul>
<b>Fleet No. Supplier:</b>	A684460
<b>Fleet No. JCPSA:</b>	2309214
<b>Maximum external dimension (eg. including legs, pipes, facade/cladding, AC units) (Length x Width X Height)</b>	
<b>Transport Company:</b>	Other
<b>Date:</b>	05.10.2023 07:52 BST
<b>Assessed by:</b>	Allan Galwas

**Flagged items**

1 flagged

External Inspection


**Keys**

No

One missing key

---

<b>External Inspection</b>	1 flagged, 20 / 29 (68.97%)
<b>Roof</b>	Good
<b>Paint</b>	Fair
<b>Score justification:</b>	Starting to show age, minor rust
<b>Walls</b>	Good
<b>Floor Beams</b>	Good
<b>Windows</b>	Good
<b>Shutters</b>	N/A
<b>Doors</b>	Good
<b>Keys</b>	No
One missing key	
<b>General Condition</b>	Good
<b>Overall External Assessment Summary</b>	Starting to show age

<b>Internal Inspection</b>	40 / 56 (71.43%)
<b>Celling</b>	Good
<b>Walls</b>	Good
<b>Windows</b>	Good
<b>Partition Doors / Keys</b>	Fair
<b>Score justification:</b>	Missing keys 1x external 1x internal
<b>Trims</b>	Good
<b>Floor</b>	Fair
<b>Score justification:</b>	Damaged vinyl
 <p>Photo 10</p>	
<b>Other fittings</b>	Toilet
<b>Toilet/WC</b>	Good
<b>Toilet cubicles</b>	Good
<b>Cistern</b>	Good
<b>Handwash Basin</b>	Good
<b>Urinals</b>	Good
<b>Water heater</b>	Good
<b>Electrics</b>	Good
<b>General Condition</b>	Good
<b>Overall Internal Assessment Summary</b>	Floor vinyl slightly damaged

## Media summary



Photo 1



Photo 2



Photo 3



Photo 4




Photo 5



Photo 6



Photo 7




Photo 8



Photo 9



Photo 10