



Unit Assessment Sheet

Complete

Score	29 / 53 (54.72%)	Flagged items	0	Actions	0
-------	------------------	---------------	---	---------	---

2-4 External Pictures of Unit



Photo 1



Photo 2



Photo 3



Photo 4

2-4 Internal Pictures of Unit



Photo 5



Photo 6




Photo 7



Photo 8

2210364 24ft x 9ft Used AV Store

External	4 / 10 (40%)
----------	--------------

Size (Length x Width X Height): **24ft x 9ft**

Maximum external dimension (eg. including legs, pipes, facade/cladding, AC units) (Length x Width X Height):

Jack legs affect overall width (no measurements due to no access) Unit is double stacked

Specification:	Used AV Store
----------------	---------------

Color:	Grey RAL Code TBC
--------	-------------------

Windows:	N/A
----------	-----

Doors:	1
--------	---

Roof Insulation:	N/A
------------------	-----

Wall Insulation:	N/A
------------------	-----


Lifting:

	Jacklegs	Lifting Eye Top
Keys		Yes
How many keys per lock are included?		Yes
One		
Electrical		
Power in:		N/A
Consumer unit:		N/A
Lighting:		Fluorescent light
Number of lights:		1
Number of electrical sockets:		0
Number of electrical switches:		0
Heating:		N/A
Number of heaters:		0
Internal		2 / 2 (100%)
Rooms:		1
Floor finish:		Wood
Wall finish:		Galvanized Steel
Kitchen unit:		N/A
Restroom:		N/A
General		
Fleet No. Supplier:		BBN12215
Fleet No. JCPSA:		2210364
Transport Company:		Other
Date:		20.10.2023 10:40 BST
Assessed by:		Allan Galwas

External Inspection		15 / 25 (60%)
Roof		Fair
Score justification:	Restricted access, needs checking	
Paint		Fair
Score justification:	Slightly rusty + chipped	
Walls		Fair
Minor dents		
Floor Beams		Good
Windows		N/A
Shutters		N/A
Doors		Good
Keys		Yes
How many keys per lock are included?		2
General Condition		Fair
Score justification:	Old unit, showing age	
Overall External Assessment Summary	damaged paint + walls, Roof needs to be checked	


Internal Inspection	8 / 16 (50%)
----------------------------	--------------

Ceiling Rusted, signs of leak, holes not visible	Fair
---	-------------

Walls  <p>Photo 9</p>	Fair
---	-------------

Score justification:	Tiny holes in certain places
----------------------	-------------------------------------

Windows	N/A
Partition Doors / Keys	N/A
Trims	N/A

Floor  <p>Photo 10</p>	Fair
--	-------------

Score justification:	Hole in floor
----------------------	----------------------

Other fittings	N/A
Electrics	N/A
General Condition	Fair

Score justification:	Damaged floor, walls and potentially roof/ceiling
----------------------	--

Overall Internal Assessment Summary

water stains all over floor, sign of leak, (unit showing age))

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10