



Unit Assessment Sheet

Complete

Score	39 / 72 (54.17%)	Flagged items	2	Actions	0
-------	------------------	---------------	---	---------	---

2-4 External Pictures of Unit



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5

2-4 Internal Pictures of Unit



Photo 6



Photo 7




Photo 8



Photo 9

2302011 32ft x 10ft Used AV
Drying Room

Size (Length x Width X Height):

32ft x 10ft

Specification:

Used AV Drying Room

Power in:

Junction box

Consumer unit:

7 Way



Photo 10

Lighting:

Fluorescent light

Number of lights:

3

Number of electrical sockets:

3

Heating:

Downflow heater

Number of heaters:	2
Kitchen unit:	N/A
Restroom:	N/A
Color:	Blue RAL Code TBC
Lifting:	Forklift pockets Lifting Eye Top
Fleet No. Supplier:	37516
Fleet No. JCPA:	2302011
Maximum external dimension (eg. including legs, pipes, facade/cladding, AC units) (Length x Width X Height)	
Transport Company:	Other
Date:	13.10.2023 11:32 BST
Assessed by:	Allan Galwas

Flagged items

2 flagged

External Inspection

Keys

No


Internal Inspection




Walls

Bad



Photo 12

External Inspection	1 flagged, 22 / 33 (66.67%)
Roof	Good
Paint	Fair
Score justification:	Old +rusty, showing age
Walls	Good
Floor Beams	Fair
Score justification:	Potentially damaged floor beam
	
Windows	Good
Shutters	Good
Doors	Good
Keys	No
General Condition	Good
Overall External Assessment Summary	Potential structural damage + damaged paint

Internal Inspection	1 flagged, 13 / 28 (46.43%)
Celling	Good
Walls	Bad
	
Photo 12	
Score justification:	Damaged wall panel + insulation
Windows	Good
Partition Doors / Keys	N/A
Trims	Fair
	
Photo 13	
Score justification:	Tiny piece missing
Floor	Bad
Score justification:	Big crack in the floor, floor is elevated
	
Photo 14	
Other fittings	N/A
Electrics	Good
General Condition	Fair
Score justification:	Damaged floor + wall
Overall Internal Assessment Summary	Structurally damaged

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14