



Unit Assessment Sheet

Complete

Score	37 / 68 (54.41%)	Flagged items	1	Actions	0
-------	------------------	---------------	---	---------	---

2-4 External Pictures of Unit




Photo 1



Photo 2



Photo 3




Photo 4



Photo 5

2-4 Internal Pictures of Unit




Photo 6




Photo 7




Photo 8




Photo 9

2302032 21ft x 9ft Used AV Dryer

Size (Length x Width X Height):

21ft x 9ft

Specification:

Used AV Dryer

Power in:

32A power plug

Consumer unit:

2 Way



Photo 10

Lighting:

Fluorescent LED light

Number of lights:

3

Number of electrical sockets:

0

Heating:

N/A

Number of heaters:	0
Kitchen unit:	N/A
Restroom:	N/A
Color:	White and Blue RAL TBC
Lifting:	ISO Corners Top
Fleet No. Supplier:	BV0857
Fleet No. JCPSA:	2302032
Maximum external dimension (eg. including legs, pipes, facade/cladding, AC units) (Length x Width X Height)	
Transport Company:	Other
Date:	14.09.2023 11:34 BST
Assessed by:	Allan Galwas


Flagged items



1 flagged

External Inspection

Keys

No

External Inspection	1 flagged, 17 / 29 (58.62%)
Roof	Fair
Score justification:	Lots of rust on the roof
Paint	Fair
 <p>Photo 11</p>	
Score justification:	Rusty + losing its colour
Walls	Good
Floor Beams	Good
Windows	Good
Shutters	N/A
Doors	Fair
Keys	No
General Condition	Fair
Score justification:	Damaged paint + rusty
Overall External Assessment Summary	No structural damage, cosmetically damaged

Internal Inspection		17 / 28 (60.71%)
Celling		Good
Walls		Poor
		
	Photo 12	
Score justification:		Hole in the wall
Windows		Good
Partition Doors / Keys		N/A
Trims		Good
Floor		Poor
		
	Photo 13	
Score justification:		Vinyl is damaged + has risen leaving bumps
Other fittings		N/A
Electrics		Good
General Condition		Good
Overall Internal Assessment Summary		Internal wall damaged + damaged floor

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13