



Unit Assessment Sheet

Complete

Score	33 / 51 (64.71%)	Flagged items	0	Actions	0
-------	------------------	---------------	---	---------	---

2-4 External Pictures of Unit



Photo 1



Photo 2



Photo 3



Photo 4

2-4 Internal Pictures of Unit



Photo 5



Photo 6



Photo 7

2303112 20ft x 8ft Used Shipping Container

Size (Length x Width X Height):

20ft x 8ft

Specification:

Used Shipping Container

Power in:

N/A

Consumer unit:

N/A

Lighting:

N/A

Number of lights:

0

Number of electrical sockets:

0

Heating:

N/A

Number of heaters:

0


Kitchen unit:


N/A

Restroom:

N/A

Color:	Grey RAL Code TBC
Lifting:	ISO Corners Top ISO Corners Bottom
Fleet No. Supplier:	BV0156
Fleet No. JCPSA:	2303112
Maximum external dimension (eg. including legs, pipes, facade/cladding, AC units) (Length x Width X Height)	
Transport Company:	Other
Date:	21.09.2023 10:25 BST
Assessed by:	Allan Galwas

External Inspection	17 / 24 (70.83%)
Roof	Good
Paint	Fair
 <p>Photo 8</p>	
Score justification:	Paint slightly damaged , showing age
Walls	Good
Floor Beams	Good
Windows	N/A
Shutters	N/A
Doors	Good
Keys	N/A
General Condition	Good
Overall External Assessment Summary	Good condition, paint damaged

Internal Inspection	11 / 16 (68.75%)
Celling	Good
Walls	Fair
 <p>Photo 9</p>	
Score justification:	Few tiny holes
Windows	N/A
Partition Doors / Keys	N/A
Trims	N/A
Floor	Good
Other fittings	N/A
Electrics	N/A
General Condition	Good
Overall Internal Assessment Summary	Good condition, little holes in the walls

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9