



## **Unit Assessment Sheet**

Complete

**43 / 72 (59.72%)** Flagged items Score 1 Actions 0

### 2-4 External Pictures of Unit













Photo 4

Photo 6

#### 2-4 Internal Pictures of Unit









Photo 7

Photo 8

Photo 9

Photo 10

2308183 32ft x 10ft Used AV Open Plan Office

Size (Length x Width X Height): 32ft x 10ft x 8ft7

**Specification:** Used AV Open Plan Office

Power in: 32A power plug

**Consumer unit:** 3 Way



Photo 11

| Lighting:                     | Fluorescent light |
|-------------------------------|-------------------|
| Number of lights:             | 3                 |
| Number of electrical sockets: | 8                 |
| Heating:                      | N/A               |

1/8 Private & confidential



| Number of heaters:  | 0                         |
|---|---------------------------|
| Kitchen unit:   | N/A                       |
| Restroom:   | N/A                       |
| Color:  | Blue + White RAL Code TBC |
| Lifting:  | Lifting Eye Top           |
|   | Lifting Eye Bottom        |
| Fleet No. Supplier:   | GT32618                   |
| Fleet No. JCPSA:  | 2308183                   |
| Maximum external dimension (eg. including legs, pipes, facade/cladding, AC units) (Length x Width X Height) |                           |
| Transport Company:  | Other                     |
| Date:   | 21.09.2023 11:44 BST      |
| Assessed by:  | Allan Galwas              |

Private & confidential 2/8



Flagged items

External Inspection

Keys

No

Private & confidential 3/8



# **External Inspection** 1 flagged, 22 / 33 (66.67%) Good Roof **Paint** Photo 12 Paint starting to come off, Score justification: showing age Walls **Floor Beams** Good Windows Good **Shutters** Good **Doors** Good One is locked Keys No **General Condition** Good

**Overall External Assessment Summary** 

Good condition, walls showing

age

Private & confidential 4/8



# Internal Inspection17 / 28 (60.71%)CellingGoodWallsFair

## Score justification:

Stained wall panels + small holes all around





Photo 13

Photo 14

| Windows                | Good |
|------------------------|------|
| Partition Doors / Keys | N/A  |
| Trims                  | Good |
| Floor                  | Poor |





Photo 15

Other fittings

Score justification:

| Extremely | rusty | + | damaged |
|-----------|-------|---|---------|
|           |       |   | vinyl   |

N/A

| Electrics                           | Good                                       |
|-------------------------------------|--|
| General Condition                   | Fair                                       |
| Score justification:                | Damaged floor , minor defects on the walls |
| Overall Internal Assessment Summary | Fair condition, structurally good          |

Private & confidential 5/8



# Media summary



Photo 1



Photo 3



Photo 5



Photo 2



Photo 4



Photo 6

Private & confidential 6/8





Photo 7



Photo 9



Photo 11



Photo 8



Photo 10



Photo 12





Photo 13



Photo 15



Photo 14



Photo 16

Private & confidential 8/8