



Unit Assessment Sheet

Complete

Score	61 / 89 (68.54%)	Flagged items	0	Actions	0
-------	------------------	---------------	---	---------	---

2-4 External Pictures of Unit



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5

2-4 Internal Pictures of Unit




Photo 6




Photo 7



Photo 8



Photo 9




Photo 10



Photo 11

2309218 13ft x 9ft Used AV 2+1
Toilet Block FR

Size (Length x Width X Height):

13ft x 9ft

Specification:

Used AV 2+1 Toilet Block FR

Power in:

32A power plug

Consumer unit:

3 Way



Photo 12

Lighting:

Fluorescent LED light

Number of lights:

2


Number of electrical sockets:

0

Heating:

N/A

Number of heaters:	0
Kitchen unit:	N/A
Restroom:	Yes
Type:	2 Gents + 1 Ladies
Color:	White RAL Code TBC
Lifting:	Jacklegs
Fleet No. Supplier:	A540043
Fleet No. JCPSA:	2309218
Maximum external dimension (eg. including legs, pipes, facade/cladding, AC units) (Length x Width X Height)	
Transport Company:	Other
Date:	04.10.2023 09:01 BST
Assessed by:	Allan Galwas

External Inspection	18 / 25 (72%)
Roof	Good
Paint	Fair
Score justification:	Starting to peel
	
Photo 13	
Walls	Good
Floor Beams	Good
Windows	N/A
Shutters	N/A
Doors	Good
Keys	Yes
How many keys per lock are included?	1
General Condition	Good
Overall External Assessment Summary	Good condition, paint starting to peel

Internal Inspection	39 / 52 (75%)
Ceiling	Good
Walls	Good
Windows	N/A
Partition Doors / Keys	Good
Trims	Good
Floor	Good
Other fittings	Toilet
Toilet/WC	Good
Toilet cubicles	Good
Cistern	Good
Handwash Basin	Good
Urinals	Good
Water heater	Good
Electrics	Good
General Condition	Good
Overall Internal Assessment Summary	No internal damage

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13